



SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 101

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/10/94

TIME: 1515

DIRECTION: North

View of the 10,000 gallon above ground storage tanks (ASTs) located in the north-west corner of the facility. These 6 tanks were labeled fuel oil.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 102

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/10/94

TIME: 1516

DIRECTION: North

View of 9 additional ASTs on the north-west corner of the facility. These tanks ranged in capacity from 1,000 to 9,000 gallons.



9490353





SITE NAME: Robin Road Drum TDD#: T06-9406-006

PHOTO#: 107 PHOTOGRAPHER\WITNESS: Gomez/Reddy

DATE: 06/10/94 TIME: 1523 DIRECTION: SE

View of the five ASTs located at the east side of the facility, behind the main warehouse.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 108 PHOTOGRAPHER\WITNESS: Gomez/Reddy

DATE: 06/10/94 TIME: 1524 DIRECTION: SE

Closeup view of a 16,000 gallon AST at the east end of the facility. Notice placards.





SITE NAME: Robin Road Drum TDD#: T06-9406-006
 PHOTO#: 111 PHOTOGRAPHER/WITNESS: Gomez/Reddy
 DATE: 06/10/94 TIME: 1529 DIRECTION: East
 Panoramic view of the Mat Chemicals Inc. facility.

SITE NAME: Robin Road Drum TDD#: T06-9406-006
 PHOTO#: 112 PHOTOGRAPHER/WITNESS: Gomez/Reddy
 DATE: 06/10/94 TIME: 1529 DIRECTION: East
 View of drums located south of the facility's main warehouse.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 109

PHOTOGRAPHER\WITNESS: Gomez/Reddy

DATE: 06/10/94

TIME: 1528

DIRECTION: East

55-gallon drums located south of the main warehouse. Notice loading dock filled with rain water.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 110

PHOTOGRAPHER\WITNESS: Gomez/Reddy

DATE: 06/10/94

TIME: 1529

DIRECTION: North

Panoramic view of the Mat Chemicals Inc. facility.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 208

PHOTOGRAPHER\WITNESS: Gomez/Reddy

DATE: 06/13/94

TIME: 0855

DIRECTION: South

Drums staged in Warehouse # 2. These drums were generally unlabeled and in advanced stages of deterioration.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 209

PHOTOGRAPHER\WITNESS: Gomez/Reddy

DATE: 06/13/94

TIME: 0855

DIRECTION: West

Drums located outdoors near the receiving dock.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 224

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/17/94

TIME: 1330

DIRECTION: South

Closeup view of Olefin (C1620) labpack.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 301

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/17/94

TIME: 1335

DIRECTION: SW

Panoramic view of the labpacks at the Robin Road Drum Site.





SITE NAME: Robin Road Drum TDD#: T06-9406-006
 PHOTO#: 312 PHOTOGRAPHER/WITNESS: Gomez/Reddy
 DATE: 06/17/94 TIME: 1345 DIRECTION: South
 Closeup of 1-gallon cans containing Fuel Blend Oil. Generator: Ethyl Corporation.

SITE NAME: Robin Road Drum TDD#: T06-9406-006
 PHOTO#: 313 PHOTOGRAPHER/WITNESS: Gomez/Reddy
 DATE: 06/17/94 TIME: 1345 DIRECTION: South
 A number of jars and small cans were located inside the fenced area.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 314

PHOTOGRAPHER\WITNESS: Gomez/Reddy

DATE: 06/17/94

TIME: 1345

DIRECTION: East

A large number of containers, apparently filled with hydrocarbons, were encountered through the site.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 315

PHOTOGRAPHER\WITNESS: Gomez/Reddy

DATE: 06/17/94

TIME: 1345

DIRECTION: East

Containers with hydrocarbon contents.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 113 **PHOTOGRAPHER\WITNESS:** Gomez/Reddy

DATE: 06/10/94

TIME: 1629

DIRECTION: South

View of the pond at the south east corner of the facility. It appears to be the receiving body for all the rain water flowing into and out of the site.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006


PHOTO#: 201 **PHOTOGRAPHER\WITNESS:** Gomez/Reddy

DATE: 06/13/94

TIME: 0843

DIRECTION: North

TAT members conducting air monitoring operations around ASTs.





SITE NAME: Robin Road Drum **TDD#:** T06-9406-006

PHOTO#: 202 **PHOTOGRAPHER/WITNESS:** Gomez/Reddy

DATE: 06/13/94 **TIME:** 0844 **DIRECTION:** North

TAT members conducting air monitoring operations utilizing organic vapor analyzer (OVA).

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 203 **PHOTOGRAPHER/WITNESS:** Gomez/Reddy

DATE: 06/13/94 **TIME:** 0847 **DIRECTION:** North

TAT members conducting air monitoring operations outdoors.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 204

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/13/94

TIME: 0850

DIRECTION: North

TAT member conducting air monitoring operations inside main warehouse. This particular container displayed a high organic content based on the OVA.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 205

PHOTOGRAPHER/WITNESS: Gomez/Reddy


DATE: 06/13/94

TIME: 0851

DIRECTION: North

Closeup view of a drum labeled isopropanol, flammable liquid.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 206

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/13/94

TIME: 0852

DIRECTION: North

View of drum labeled RMS-0967, an Exxon Chemical Corporation product. This material was labeled non-hazardous.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 207

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/13/94

TIME: 0852

DIRECTION: East

Open top 55-gallon drums with apparently similar contents.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 212 PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/13/94 TIME: 1020 DIRECTION: NE

The secondary containment of AST # 7 contained contaminated rain water.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 213 PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/16/94 TIME: 0928 DIRECTION: North

TAT member sampling AST# 3.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 214

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/16/94

TIME: 0930

DIRECTION: NW

TAT member collecting a sample from AST# 1.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 215

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/16/94

TIME: 1025

DIRECTION: North

TAT members collecting samples from the containers in the facility's main warehouse





SITE NAME: Robin Road Drum **TDD#:** T06-9406-006
PHOTO#: 216 **PHOTOGRAPHER/WITNESS:** Gomez/Reddy
DATE: 06/16/94 **TIME:** 1050 **DIRECTION:** NW
 TAT members sampling the site's ASTs utilizing a manlift.

SITE NAME: Robin Road Drum **TDD#:** T06-9406-006
PHOTO#: 217 **PHOTOGRAPHER/WITNESS:** Gomez/Reddy
DATE: 06/16/94 **TIME:** 1130 **DIRECTION:** South
 TAT member during field screening operations.





SITE NAME: Robin Road Drum TDD#: T06-9406-006

PHOTO#: 218 PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/17/94 TIME: 1330 DIRECTION: South

View of some of the labpacks encountered at the site. Most of these labpacks were sealed and hence not sampled.


SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 219 PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/17/94 TIME: 1330 DIRECTION: South

Closeup view of labpack labeled N-Hexylamine, flammable liquid, corrosive N.O.S.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 220

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/17/94

TIME: 1330

DIRECTION: South

View of some of the labpacks encountered at the site. These ones were labeled Glycol Ether.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 221

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/17/94

TIME: 1330

DIRECTION: South

Closeup view of Glycol Ether DE labpacks. Manufacturer: Oxychem.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 222

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/17/94

TIME: 1330

DIRECTION: South

Closeup view of Glycol Ether DE labpacks.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 223


PHOTOGRAPHER/WITNESS: Gomez/Reddy


DATE: 06/17/94

TIME: 1330

DIRECTION: South

Closeup view of Glycol Ether DE labpacks.





SITE NAME: Robin Road Drum TDD#: T06-9406-006
 PHOTO#: 304 PHOTOGRAPHER/WITNESS: Gomez/Reddy
 DATE: 06/17/94 TIME: 1335 DIRECTION: South
 Closeup view of Triethanolamine Residue labpacks. Generator: Oxy Petrochemicals Inc.


SITE NAME: Robin Road Drum TDD#: T06-9406-006
 PHOTO#: 305 PHOTOGRAPHER/WITNESS: Gomez/Reddy
 DATE: 06/17/94 TIME: 1345 DIRECTION: West
 View of fenced area inside the facility's main warehouse. Most of the labpacks were stored inside this area.





SITE NAME: Robin Road Drum TDD#: T06-9406-006
 PHOTO#: 306 PHOTOGRAPHER/WITNESS: Gomez/Reddy
 DATE: 06/17/94 TIME: 1345 DIRECTION: North
 5-gallon buckets stored inside fenced area.

SITE NAME: Robin Road Drum TDD#: T06-9406-006
 PHOTO#: 307 PHOTOGRAPHER/WITNESS: Gomez/Reddy
 DATE: 06/17/94 TIME: 1345 DIRECTION: North
 5-gallon container labeled flammable liquid N.O.S., UN 1993. Generator: DOW U.S.A.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 308

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/17/94

TIME: 1345

DIRECTION: NW

5-gallon container labeled Ethyl Oil, flammable liquid.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 309

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/17/94

TIME: 1345

DIRECTION: South

Several 5-gallon containers were stored within the fenced area inside the facility's main warehouse.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 310

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/17/94

TIME: 1345

DIRECTION: South

A number of 5-gallon containers with unknown contents were located throughout the site.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 311

PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/17/94

TIME: 1345

DIRECTION: SW

5-gallon and 1-gallon containers inside fenced area.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 316 PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/17/94 TIME: 1345 DIRECTION: East

1-gallon metal cans with flammable contents.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 317 PHOTOGRAPHER/WITNESS: Gomez/Reddy

DATE: 06/17/94 TIME: 1345 DIRECTION: South

Containers with antifreeze and other unknown contents.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 401

PHOTOGRAPHER\WITNESS: Gomez/Cornelius

DATE: 07/13/94

TIME: 0920

DIRECTION: East

TAT member collecting composite soil samples.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 402

PHOTOGRAPHER\WITNESS: Gomez/Cornelius

DATE: 07/13/94

TIME: 0922

DIRECTION: East

TAT member collecting composite soil samples.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 403 PHOTOGRAPHER/WITNESS: Gomez/Cornelius

PHOTO#: 404 PHOTOGRAPHER/WITNESS: Gomez/Cornelius

DATE: 07/13/94 TIME: 1020 DIRECTION: NE

DATE: 07/13/94 TIME: 1020 DIRECTION: NE

TAT member sampling pond sediments.

TAT member sampling pond sediments.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 405

PHOTOGRAPHER\WITNESS: Gomez/Cornelius

DATE: 07/13/94

TIME: 1025

DIRECTION: SE

Pond sediment sample.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 406

PHOTOGRAPHER\WITNESS: Gomez/Cornelius

DATE: 07/13/94

TIME: 1345

DIRECTION: North

TAT member collecting drum samples.





SITE NAME: Robin Road Drum TDD#: T06-9406-006
 PHOTO#: 407 PHOTOGRAPHER\WITNESS: Gomez/Cornelius
 DATE: 07/13/94 TIME: 1350 DIRECTION: NE
 TAT member collecting a sample from a 5-gallon container.

SITE NAME: Robin Road Drum TDD#: T06-9406-006
 PHOTO#: 408 PHOTOGRAPHER\WITNESS: Gomez/Cornelius
 DATE: 07/13/94 TIME: 1350 DIRECTION: NE
 TAT members collecting a sample from a 5-gallon container.





SITE NAME: Robin Road Drum TDD#: T06-9406-006
 PHOTO#: 409 PHOTOGRAPHER\WITNESS: Gomez/Cornelius
 DATE: 07/13/94 TIME: 1352 DIRECTION: West
 TAT member collecting a sample from a 5-gallon container.

SITE NAME: Robin Road Drum TDD#: T06-9406-006
 PHOTO#: 410 PHOTOGRAPHER\WITNESS: Gomez/Cornelius
 DATE: 07/13/94 TIME: 1354 DIRECTION: West
 TAT member collecting a sample from a 55-gallon container.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 411 PHOTOGRAPHER\WITNESS: Gomez/Cornelius

DATE: 07/13/94 TIME: 1435 DIRECTION: West

TAT member collecting a sample from a 55-gallon container.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 412 PHOTOGRAPHER\WITNESS: Gomez/Cornelius

DATE: 07/13/94 TIME: 1435 DIRECTION: NW

TAT member collecting a sample.





SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 413

PHOTOGRAPHER/WITNESS: Gomez/Cornelius

DATE: 07/13/94

TIME: 1442

DIRECTION: West

TAT members collecting drum samples.

SITE NAME: Robin Road Drum

TDD#: T06-9406-006

PHOTO#: 414

PHOTOGRAPHER/WITNESS: Gomez/Cornelius

DATE: 07/13/94

TIME: 1442

DIRECTION: West

TAT members collecting drum samples from area adjacent to the facility's loading dock.

